

**Work Order ID 59524**

Monday, June 07, 2010 7:47:02 AM



Page 1

Item ID: D044-713-015

Accept



Setup

Start



Revision ID:

Item Name: Passenger Door Window (Fits LH &amp; RH)

Stop



Start Date: 6/4/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 6/11/2010 Req'd Qty: 2.00



Customer:

Reference: Return 2010 / RA110054

Run

Start



Approvals:

Process Plan:

Date:

Tooling:

Date:

Stop



QC:

Date: 6/6/09

SPC (Y/N):

Date:

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
N/A	Rev N/A

100 QC5- Inspect part completeness to step on W/O 0.00



QC

Quality Control

Memo

0.00

110 Identify as per dwg & Stock Location: Draft 0.00

Packaging

Packaging

Memo

0.00

New labels, decals with the new batch # @ CHG001 &amp; new paperwork required.

120 QC21- Final Inspection - Work Order Release 0.00



QC

Quality Control

Memo

0.00

# Work Order ID 59524

Monday, June 07, 2010 7:47:02 AM



Page 1

Item ID: D044-713-015

Accept



Setup Start



Revision ID:

Item Name: Passenger Door Window (Fits LH & RH)

Stop



Start Date: 6/4/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 6/11/2010 Req'd Qty: 2.00



Customer:

Reference: Return 2010 / RA110054

Approvals: Process Plan: \_\_\_\_\_

Date: \_\_\_\_\_

Tooling: \_\_\_\_\_

Date: \_\_\_\_\_

Run Start



QC: J

Date: 6-06-04

SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop



Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr	Revision Nbr	
N/A	Rev N/A	

100

QC5- Inspect part completeness to step on W/O

0.00

REFERENCE ONLY

QC

Quality Control

Memo

0.00

6/10/04

(Y2)

Original B51003 @ CHG001.  
Kits were complete & in good condition.

110

Identify as per dwg & Stock Location: \_\_\_\_\_

0.00

Packaging

Packaging

Memo

0.00

New labels, decals with the new batch # @ CHG001 & new paperwork required.

120

QC21- Final Inspection - Work Order Release

0.00

QC

Quality Control

Memo

0.00